

Project: Restauration of the Palace in Pland, Palace from XVII century.

www.ASTRAGIS.com info@astragis.com Zagórze 27, 05-079 Okuniew, POLAND tel:0048 501545106


LASERSCANNING - PHOTOGRAMMETRY - SOFTWARE



The Palace was burned and destroyed.



164 Scannen made to cover all of the details.



Accuracy <1cm,
Calculations by ASCAN



Works out made by ASCAN Software.



Copyright: ASTRAGIS, 2011